COMPLETION REPORT

1. Name of Work :**Pot hole filling in Ward No. 13, in shettyhalli Sub- Division**
2. Sanctioned Estimate No. & Dt : 260/3-12-13
3. Head of Account which is chargeable : P2019
4. Work Order No. & Dt : 177/20-12-13
5. Name of Contractor : **KRIDL**
6a. Time Stipulated for completion of work : 90 dys
6b. Delay in execution of work : 356 dys.
7. Measurement recorded in : M.B. No. 1694/11-12
8. Check Measurement of the Asst. : M.B. No. 1694/11-12
   Page No. 169346-48
   Asst. Exe. Eng / Exe. Eng :
   Page No. 169346-48
9. Name of the office/official : AGE (SSD)
   incharge of the work : Nagabhushan. G
10. a) Asst. Engineer
    b) Asst. Exe. Engineer : Jayalingappa

Sanctioned Estimated Amount	Amount claims as per actually vide as per bills	Difference	
		Excess	Savings
5,00,000=00	542296	42296=00	—

1) Certified that the above has been completed within the stipulated time noted in the work order.
2) Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3) Certified that the above work has been executed by the contractor satisfactorily in accordance with the specifications as embodied in the agreement.

ASST. ENGINEER

ASST. EXECUTIVE ENGINEER
BRUHATH BANGALORE MAHANAGARA PALIKE

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Zone, Bangalore-57.